


Transitional Milling



- 1. Lay out and mark transition areas to be milled parallel to existing surfaces to remain.**
- 2. Mill existing asphalt to a depth of 1-1/2", utilizing machinery designed specifically for this operation.**
- 3. Clean the entire area of repair and dispose of all debris offsite.**
- 4. Install specified finish material.**